Wednesday, 3/12/2008 1:51:25 PM **Process Sheet** : BAR **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer \* Job Number 37885 : 10390 Estimate Number : D3197041 Part Number P.O. Number . D3197 REV B **Drawing Number** This Issue : 3/12/2008 S.O. No. : : N/A : NC Project Number Prsht Rev. : B : MACHINED PARTS : 1.1 Type **Drawing Revision** First Issue : 35281 Material Previous Run : 3/28/2008 Qty: 12 Um: Due Date Written By Checked & Approved By JLM New Issue Comment Est Rév:B As per Rev B 06-03-10. JLM **Additional Product** Job Number: Description: Seq. #: Machine Or Operation: 7075-T73 Round Bar 1" OD 1.0 M7075T73R1000 Comment: Qty.: 2.5410 f(s)/Unit Total : 30.4920 f(s) Material: 7075-T73 (QQ-A-200/11) or (QQ-A-225/9) 1" OD (M7075T73R1.000) H106070 Identify for D3197-1 Batch: M107513 2.0 Comment: BAND SAW 080401 Cut blanks: 29.125", long HAAS CNC VERTICAL MACHINING #1 3.0 HAAS1 Comment: HAAS CNC VERTICAL MACHINING #1

Each

Machined Munually

2-Machine D3197-1 as per Folio FA340 and Dwg D3197

3-Deburr

QC2 4.0 .





• Comment: INSPECT PARTS AS THEY COME OFF MACHINE

1-Face ends to lenght per dwg D3197

## Dart Aerospace Ltd

W/O:			WORK ORDER	CHANGES				
DATE	STEP	PROC	EDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·					
		•						
		4						
Part No	•	PAR #:	_ Fault Category:	NCR: Ye	s No DQ	A:	_ Date: _	
				QA	: N/C Close	d:	_ Date: _	

		WORK ORD	ER NON-CONFORMANO	E (NCR)			
	Description of NC		Corrective Action Section B		Varification	Anneous	
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector
				·			
							·
			•				
	STEP	STED Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Action Description	STEP Description of NC Section A Initial Action Description Sign &	STEP Section A Initial Action Description Sign & Section C	STEP Description of NC Section A Section B Initial Action Description Sign & Section C Chief Eng

Wednesday, 3/12/2008 1:51:25 PM Date; Kim Johnston User: **Process Sheet** Drawing Name: BAR Customer: CU-DAR001 Dart Helicopters Services Job Number: 37885 Part Number: D3197041 Job Number: Description: Seq. #: **Machine Or Operation:** CONVENTIONAL LATHE LATHE CONV 5.0 Comment: CONVENTIONAL LATHE 08/04/11 Chamfer as per Dwg D3197 SECOND CHECK 6.0 Comment: SECOND CHECK HAND FINISHING RESOURCE #1 7.0 HAND FINISHING1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 POWDER COATING m 106442 Comment: POWDER COATING Powder Coat Grey Sandtex (Ref: 4.3.5.6) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 QC3 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION Lanyard ass'y D26905 10.0 2.0000 Each(s)/Unit Total: Comment: Qty.: 24.0000 Each(s) Pick: **Qty Part Number** 2 D2690-5 D32421 11.0 2.0000 Each(s)/Unit Total: 24.0000 Each(s) Comment: Qty.: Pick: Description Batch TAG (33531) 6 × 137934 (5 × 5) **Qty Part Number** 2 D3242-1

## Dart Aerospace Ltd

W/O:		WORK ORDER CHANG	ES					
DATE	STEP	PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-	·	
Part No	:	PAR #: Fault Category:	_ NCR:	Yes	No <b>DQ</b>	<b>\</b> :	Date:	
				QA:	N/C Close	d:	Date:	<del></del>

NCR:		WORK ORDER NON-CONFORMANCE (NCR)					
		Description of NC		Corrective Action Section B	Verification	Ammayal	
DATE	STEP	Section A			& Section C	Approval Chief Eng	Approval QC Inspector
		· · · · · · · · · · · · · · · · · · ·					
		· Ja					
		,	:			,	
							ļ
		·					
•							
						-	
				*			

Wednesday, 3/12/2008 1:51:25 PM Date: Kim Johnston User: **Process Sheet** Drawing Name: BAR Customer: CU-DAR001 Dart Helicopters Services Job Number: 37885 Part Number: D3197041 Job Number: Seq. #: Description: Machine Or Operation: Washer 12.0 AN960JD10 6.0000 Each(s)/Unit Total: Comment: Qty.: 72.0000 Each(s) Pick: Description Batch Washer MI. 7534 **Qty Part Number** 6 AN960JD10 D34893200 PIP PIN 13.0 2.0000 Each(s)/Unit Total: 24.0000 Each(s) Comment: Qty.: Pick: Description Batch
Pin Pin 35313 **Qty Part Number** B 37937 118 Pip Pin 2 D3489-3-200 MS21042L3 14.0 Comment: Qty.: 2.0000 Each(s)/Unit Total: 24.0000 Each(s) Pick: **Qty Part Number** Description Batch Nut (or -3) \_\_\_ 2 MS21042L3 MS27039124 15.0 2.0000 Each(s)/Unit Total: Comment: Qty.: 24.0000 Each(s) Pick: Description Qty Part Number 2 MS27039-1-24 Screw M/00277 11X M10051 13X SMALL & MEDIUM FAB RESOURCE 1 SMALL FAB 16.0 Comment: SMALL & MEDIUM FAB RESOURCE 1 Assemble D3197-041 as per Dwg D3197 INSPECT WORK TO CURRENT STEP 17.0 QC5 Comment: INSPECT WORK TO CURRENT STEP

Dart Ae	rospac	e Ltd							
N/O:			V	<b>VORK ORDER CHAN</b>	GES				
DATE	STEP	PR	OCEDURE CI	HANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							;		
				<u> </u>					
Part No	ī	PAR #:	Fault Ca	tegory:					
NCR:			WORK OR	DER NON-CONFORM					
DATE	OTED	Description of NC		Corrective Action Sec	ction B	Verificat		A	
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Approval Chief Eng	QC Inspector
			-					:	
<del></del> -							-	·	

Date: User:

Wednesday, 3/12/2008 1:51:25 PM

Kim Johnston

**Process Sheet** 

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: BAR

Job Number: 37885

Part Number: D3197041

Job Number:



Seq. #:

Machine Or Operation:

Description:

18.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:\_

ST 247

19.0

QC21

FINAL INSPECTION/W/O RELEAS



08/04/17/1


Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



mF 08-04-16

Dart Ae	rospace L	td		•					
W/O:			W	ORK ORDER CHANGES	· · ·			-	
DATE	STEP	PR	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						- <del>-</del>			
Dowt No.	_	D.D. "							
Part No	•	PAR #:	Fault Cat	egory: NC	R: Yes	No DQA	<b>7</b> :	_ Date: _	
					QA: N	/C Closed	d:	_ Date: _	
NCR:			WORK ORI	DER NON-CONFORMANCE	(NCR	()			
DATE	OTED	Description of NC		Corrective Action Section B		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section		Chief Eng	QC Inspector
				i			1		
			1 1						



DART AEROSPACE LTD	Work Order: 37885
	Part Number: D3197-
Description: RAR ASSY.	Page 1 of 1
Inspection Dwg: D3197 Rev: R	

FIRST ARTICLE INSPECTION CHECKLIST								
		First Artic	le _	Proto	type	_		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Com	ments	
29.00	±.030	29.00						
1.000	±.010	1.000						
0.063×45	1	,063×45°						
EXT ()		-500						
1.000		6000						
0 191		0.181				<u> </u>		
0,219		6.220				<del> </del>		
2.69		2.680						
.300		. 3.00			<u> </u>	<u> </u>		
1.000		1.000		<u> </u>				
-25		-2405			<u> </u>			
11,44		11,44		ļ				
2506		23.06	/		<u> </u>	<del> </del>		
		·		ļ			<del></del>	
				ļ				
						-		
			ļ					
						<del> </del>		
				<del> </del>	<del> </del>	+		
				<u> </u>				
					<u> </u>		11	
Measured by:	50	Audited by:	SF.	, P	rototype App		4/1	
	08/04/11	Date:	08/04/1	//		Date:	1.1.	
			/ /			evised by	Appro	
Rev Date	Change New Issue	Plot	3197	-041	K	J/RF		